






CINTROPUR[®] NW 18

SLEEVES 5, 10, 25, 50 & 100 µm







PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 25 with connection 3/4"

SLEEVES 5, 10, 25, 50 & 100 m μ + 150 m μ nylon

**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**




CINTROPUR® NW 25 1"


SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm




SLEEVE 50 µm



SLEEVE 100 µm





SLEEVE 150 µm nylon (washable)



CINTROPUR® NW 25 1" and 3/4"

UNIVERSAL CARTRIDGE



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] DUO 25

with ACTIVATED CARBON - NORIT ROW 0.8 SCIN



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] DUO 25

with SILIPHOS



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] DUO 25

WITHOUT ANY PELLETS



**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 25/32 TE

with activated carbon - NORIT ROW 0.8 SCIN



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 25/32 TE

with POLYPHOSPHAT (SILIPHOS)

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA




CINTROPUR[®] NW 32


SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm




SLEEVE 50 µm



SLEEVE 100 µm



SLEEVE 150 µm nylon (washable)




CINTROPUR[®] NW 50


SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm



SLEEVE 50 µm








SLEEVE 100 µm



CINTROPUR[®] NW 62

SLEEVES 5, 10, 25, 50 & 100 µm






PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 75

SLEEVES 5, 10, 25, 50 & 100 µm




PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR® NW 50/62/75

SLEEVES 150 µ nylon




**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR® NW 50/62/75

SLEEVES 300 µ nylon




**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 50/62/75 TE

with activated carbon - NORIT ROW 0.8 SCIN

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 50/62/75 TE

with POLYPHOSPHAT (SILIPHOS)

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA

